03500.016069

Con C

FEBOTA	IN THE UNITED STATES PAT	ENT A	ND TRADEMARK OFFICE
TRADENA	Min re Patent of:	)	
THE WAY	TADASHI HAYASHI	:	Examiner: Iraj Mohandesi  Group Art Unit: 2834
	Appl. No.: 10/022,338	) :	Group The Office 2004
	Filed: December 20, 2001	)	
	For: CONTROL APPARATUS FOR VIBRATION TYPE ACTUATOR	)	Certificate
	VIBRATION TIPE ACTUATOR		FEB 1 4 2005
	U.S. Patent No.: 6,812,618 B2	:	of Correction
	Issued: November 2, 2004	:	February 7, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

### CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

02/14/2005 SDENBOB1 00000061 6812618

01 FC:1811 100.00 0P

MAR 0 8 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Michael J. Didas Attorney for Patentee Registration No. 55,112

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

MJD:eyw

DC-MAIN 191105 v1

#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,812,618 B2

**DATED** 

November 2, 2004

INVENTOR(S) :

TADASHI HAYASHI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 2:

Line 7, "can not" should read --cannot--.

Line 14, "can not" should read --cannot--.

#### COLUMN 3:

Line 18, "in a the modification" should read --in a modification--.

#### COLUMN 4:

Line 55, "can not" should read --cannot--.

#### COLUMN 6:

Line 2, "as" should be deleted.

#### COLUMN 9:

Line 24, "element ¶" should read --element--.

Line 38, "element ¶" should read --element--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

MAR 0 8 2005

PATENT NO. 6,812,618 B2

No. of add'l. copies @ 30¢ per page

**\_\_\_\_** 

Form PTO 1050 (Rev. 3-82) (Form#30)

# PRINTER'S TRIM LINE

#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,812,618 B2

**DATED** 

November 2, 2004

INVENTOR(S) :

TADASHI HAYASHI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 10:


Line 28, "element ¶" should read --element--.

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,812,618 B2</u>

No. of add'l. copies @ 30¢ per page

MAR OR ZONS



#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### CERTIFICATE OF CORRECTION

PATENT NO.

6,812,618 B2

**DATED** 

November 2, 2004

INVENTOR(S) :

TADASHI HAYASHI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 2:

Line 7, "can not" should read --cannot--. Line 14, "can not" should read --cannot--.

#### **COLUMN 3:**

Line 18, "in a the modification" should read --in a modification--.

#### COLUMN 4:

Line 55, "can not" should read --cannot--.

#### COLUMN 6:

Line 2, "as" should be deleted.

#### COLUMN 9:

Line 24, "element ¶" should read --element--. Line 38, "element ¶" should read --element--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

MAR 0 8 2005

No. of add'l. copies @ 30¢ per page

PATENT NO. 6,812,618 B2

## Stable Here Ouly! PRINTER'S TRIM

UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

6,812,618 B2

**DATED** 

November 2, 2004

INVENTOR(S) :

TADASHI HAYASHI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 10:

Line 28, "element \nabla" should read --element--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. 6,812,618 B2

No. of add'l. copies @ 30¢ per page

MAR 0 8 2005



Form PTO 1050 (Rev. 3-82) (Form#30)